


## 5775 Series Shower Valve Rebuild Kit



Part No. 100034

### ► **Description**

A complete internal rebuild kit for the I-CON 5775 Series Shower Valve. Kit includes the valve's seat seals, pressure separation gasket and miscellaneous small parts allowing for the rebuilt valve to meet the standards of a new I-CON 5775 Series Shower Valve.


### **Specifications**

- (1) Seat Seal Assembly
- (1) Pressure Separation Gasket
- (1) Support Ring
- (1) Spring
- (2) Screws

### ► **Accessories**

See Accessories Section of the I-CON catalog or contact our Customer Service Team for details.



 **WARNING:** Cancer and Reproductive Harm - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

This space is for Architect/Engineer approval

The information contained in this document is subject to change without notice.